

The instruction how to prepare the UZ50 for the transport in horizontal position.

In the case that your demo car doesn't have sufficient height for transport in the normal, basic position, you can lay the machine to horizontal position.

Follow the points:

1/ Adjust angle 15 degrees

2/ Scroll down with the machine into the lowest position and fix this position by the belt.




3/ By the help feeding wheels attach the suitable wood boards according the picture.



4/ Prepare suitable palette and shims with soft pillow.



5/ Use the shims on places according the pictures



6/ Lay the UZ50 on the pallet according the picture.



7/ Fasten the machine on the pallet by the following way



8/ The UZ50 is ready for transport.